

EAST - [golf cart:2]

File View Edit Tools Window Help

Drafts

- ISNR:
- BRS:
- BRS: bumper with bracket with
- BRS:
- BRS:
- BRS: bipart\$
- BRS: 11 and
- BRS: 17 and

Pending

Active

- L1: (262) (248/222.12).CCLS.
- L2: (0) 11 and barb with deform
- L4: (0) 13 and barb with deform
- L5: (3) 13 and barb
- L3: (512) (248/222.51-222.52).CCLS.
- L6: (311) (296/97.9).CCLS.

Failed

- (0) ("296/214.ccls.-296/224.ccls.").CCLS.
- (0) ("296/\$.ccls.").CCLS.
- (0) ("296/\$.ccls.").CCLS.
- (0) 11 and (stop adj2 block))
- (0) M.E.D.

Search List Browse Queue

DBs USPAT

☒ Highlight all hit terms initially

296/97.9

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (13)

UDC

Queue

Trash

	U	I	Document ID	Issue Dat	Page	Title	Current
1	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6669149 B2	20031230	12	Fixing member for fixing an object to be	248/71
2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5407363 A	19950418	11	Floating panel mounting system for electrical c	439/546
3	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4422608 A	19831227	7	Panel hanger	248/205.4
4	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4319531 A	19820316	13	Shelf mounting system, parts therefor and meth	108/152
5	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3289992 A	19661206	4	Hook structure for perforated boards	248/220.3
6	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3235219 A	19660215	3	Detachably mountable article support	248/239
7	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3179367 A	19650420	12	Plastic quarter turn shelf support	248/239
8	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 2909352 A	19591020	3	Fastening device	248/239
9	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6669263 B2	20031230	16	Attachment devices	296/97.9
10	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6511116 B1	20030128	7	Mounting bracket for vehicle visor and metho	296/97.9
11	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6511029 B2	20030128	16	Bracket for mounting an accessory on vehicle bo	248/224.8
12	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6340193 B1	20020122	25	Bracket for installations of subsid	296/97.9
13	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5765897 A	19980616	9	Twist-in visor mount	296/97.9

NUM

EAST - [golf cart:2]

FileViewEditToolsWindowHelp

Drafts

ISNR:

BRS:

BRS: bumper with bracket with

BRS:

BRS:

BRS: bipart\$

BRS: 11 and

BRS: 17 and

Pending

Active

L1: (262) (248/222.12).CCLS.

L2: (0) 11 and barb with deform

L4: (0) 13 and barb with deform

L5: (3) 13 and barb

L3: (512) (248/222.51-222.52).CCLS.

L6: (311) (296/97.9).CCLS.

Failed

(0) ("296/214.ccls.-296/224.ccls.").CCLS.

(0) ("296/\$.ccls.").CCLS.

(0) ("296/\$.ccls.").CCLS.

(0) 11 and (stop adj2 block))

(0) M.E.D.

SearchListBrowseQueue

DBsUSPAT

☒ Highlight all hit terms initially

296/97.9

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (13)

UDC

Queue

Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error I
1	IS&R	L1	262	(248/222.12).CCLS.	USPA T	2004/08/1 6 06:02		
2	BRS	L2	0	11 and barb with deform	USPA T	2004/08/1 6 06:02		
3	BRS	L4	0	13 and barb with deform	USPA T	2004/08/1 6 06:03		
4	BRS	L5	3	13 and barb	USPA T	2004/08/1 6 06:03		
5	IS&R	L3	512	(248/222.51-222.52).C CLS.	USPA T	2004/08/1 6 06:31		
6	IS&R	L6	311	(296/97.9).CCLS.	USPA T	2004/08/1 6 06:32		

NUM

DetailsHTML